



RESEARCH&DEVELOPMENT OF AMERICA, INC.

5420 DANIELS STREET STE A, CHINO CALIF. 91710 · (800)634-9166 · (909)628-4722 · FACSIMILE (909)591-2198

www.yoshimura-rd.com

052HA152010

Timing Inspection Plug



Instructions:

1. Remove stock timing inspection plug.
2. Remove stock rubber o-ring from timing inspection plug and install on Yoshimura timing inspection plug.
3. Install Yoshimura timing inspection plug.
Torque to 7.4 lb-ft (10 Nm).

If safety wire is required, loop safety wire through the holes drilled in the plug to optional case saver kit or to secure location.



RESEARCH&DEVELOPMENT OF AMERICA, INC.

5420 DANIELS STREET STE A, CHINO CALIF. 91710 · (800)634-9166 · (909)628-4722 · FACSIMILE (909)591-2198

www.yoshimura-rd.com

052HA152010

Timing Inspection Plug



Instructions:

1. Remove stock timing inspection plug.
2. Remove stock rubber o-ring from timing inspection plug and install on Yoshimura timing inspection plug.
3. Install Yoshimura timing inspection plug.
Torque to 7.4 lb-ft (10 Nm).

If safety wire is required, loop safety wire through the holes drilled in the plug to optional case saver kit or to secure location.



RESEARCH&DEVELOPMENT OF AMERICA, INC.

5420 DANIELS STREET STE A, CHINO CALIF. 91710 · (800)634-9166 · (909)628-4722 · FACSIMILE (909)591-2198

www.yoshimura-rd.com

052HA152010

Timing Inspection Plug



Instructions:

1. Remove stock timing inspection plug.
2. Remove stock rubber o-ring from timing inspection plug and install on Yoshimura timing inspection plug.
3. Install Yoshimura timing inspection plug.
Torque to 7.4 lb-ft (10 Nm).

If safety wire is required, loop safety wire through the holes drilled in the plug to optional case saver kit or to secure location.



RESEARCH&DEVELOPMENT OF AMERICA, INC.

5420 DANIELS STREET STE A, CHINO CALIF. 91710 · (800)634-9166 · (909)628-4722 · FACSIMILE (909)591-2198

www.yoshimura-rd.com

052HA152010

Timing Inspection Plug



Instructions:

1. Remove stock timing inspection plug.
2. Remove stock rubber o-ring from timing inspection plug and install on Yoshimura timing inspection plug.
3. Install Yoshimura timing inspection plug.
Torque to 7.4 lb-ft (10 Nm).

If safety wire is required, loop safety wire through the holes drilled in the plug to optional case saver kit or to secure location.